

TECHNICAL BULLETIN: N°54 – W.53

Hands-free Systems and Speakerphones

PSUT and Soft

This software version for **Parrot Software Update Tool (PSUT ver_3.5.0.0)** is available from the Parrot website:

This version is available from the Parrot Website at <http://www.parrot.com/uk/support/downloads>

PSUT can only be downloaded with Windows. So it's impossible to update a MKi product with a Mac computer.

Now, on the technical support website, we add links to download a "plf" files for MKi products:

Parrot MKi

MKi9000		SW : 1.24	- The 1.24 SW is available since W49 for all languages. This version is available on PSUT.
MKi9100		SW : 1.24	- The 1.24 SW is available since W49. This version is available on PSUT.
MKi9200		SW : 1.24	- The 1.24 SW is available since W49. This version is available on PSUT.

MKi9000 - MKi9100 - MKi9200

A new software version **1.24** for product **MKi9000/MKi9100/MKi9200** is validated **OK FOR PROD** for M1 TTS: ENG, FR, IT, NL, PT, SP , US, ME and GE.

This version add some modification : You

SW : 1.24 - MKi9000 – MKi9100 –MKi9200 Modification list:

1/ Selection language at boot.

The first boot will be longer than before.

At the first boot, selection of the language is asked (selection by rotator or by press on the green button).

- During this time nothing can be done: BT visibility is OFF, no play source is available....

- After the selection the MKi reboots

- [MKi9000]: Menu language play prompt of the language in progress

"**language:** English"... Then turn rotator to select another one.

- [MKi9000]: New prompt available "**Software updated. Please wait**" before reboots.

2/ Factory settings

The selected language is unselected after a factory setting (menu on MKi9100/MKi9200, simultaneous press on button green+button red on MKi9000).

=> Then the language selection is asked again

Parrot UNIKA

UNIKA	MKi9000 since SW: 1.12 MKi9100 since SW: 1.12 MKi9200 since SW: 1.12	Software version will be updated by Parrot MKi music cable (USB)
-------	--	--

This is the new universal Steering Wheel Command interface for MKi series and Parrot RKi8400.

With MKi Series:

Since **1.12** Parrot MKi software versions, Parrot UNIKA is compatible with MKi series.

- With **MKi9100**: the display must have the 3.1 software version, you can check this version by selecting: *Setting/ Advanced setting/Information/ Display version*

The right replacement MKi9100 screens have a different index in Parrot part number: **PI020154AD**

- With **MKi9200**, you don't need to change the display.
- With **MKi9000**, there is no change.

If you have a proposal to build with MKi only, please use the reference PI090020AA

With RKi8400:

Now, products are available.

- Technical information and vehicle compatibility database for UNIKA and RKi are online : <http://www.parrot.com/uk/support/onlinehelpguides/unika>

Parrot RKi8400

Parrot RKi8400	SW: 2.11	Software version is available since W48, and available on PSUT
----------------	----------	--

Software version **2.11** for product **RKi8400** is validated **OK FOR PROD** for all TTS.

RKi8400 Modification list:

General improvements :

- "Disable synchro" pairing mode is now functional.
- The car kit remains ON longer when turning it off during a call.
- Fix a bug with few music files causing a decreased sound quality with iPods.
- Improve the RDS frequency switch.

TTS availability?

- British English (EN) / American English (US) / French (FR) / German (GE) / Italian (IT) / Spanish (SP) / Dutch (NL) / Mexican (ME) / Portuguese (PT)

Parrot CK

CK3000 Evo		SW : 5.21	- The SW 5.21 is available since W29.
CK3100 LCD		SW : 4.21	- The SW 4.21 is available since W.45
CK3200 Colors		SW : 2.12	- The SW 2.12 is available since W.14 It resolves audio bug with the iPhone. Better compatibility with phones (Nokia E51, Casio Boulder, Motorola U9...)

Parrot CK3000 Evolution :

A new software update for Parrot CK3000 Evolution (**version 5.21**) is now available from the Parrot Software Update Tool.

Languages available:

English, French, Spanish, Portuguese, German, Dutch, Italian, Danish, Swedish, Norwegian, Russian, Czech, Polish, Turkish, Greek, Japanese, Chinese, Arab, Hebrew, Taiwanese

General improvements:

- [Nokia Symbian] Fix volume changed during communication not saved after power Off
- [Nokia]: Fix disconnection issues with several Nokia phones
- [Casio Boulder] Add special pairing mode with pin code 0000 (long press Red button)

Note :

FoB (specific CK3000 update via Bluetooth) from 5.20 to 5.21 does not work with customs Toyota and ProSeries

Parrot CK3100 LCD :

The SW version 4.21 is validated OK FOR PROD. This software version is already available on the PSUT.

Languages available :

- English, French, Spanish, Portuguese, German, Dutch, Italian, Danish, Swedish, Norwegian, Russian, Czech, Polish, Turkish, Greek, Japanese, Chinese, Arab, Hebrew, Korean

4.21 Release note:

- Fix ring tone issue with some phones: Nokia, Blackberry, etc...

Parrot CK3200 LS Colors :

The SW version 2.12 is validated OK FOR PROD for all languages zones

Release note:

- Compatibility with Samsung U600, Nokia E51, Casio Boulder

Parrot MK

MK6000		SW : 1.03a	- SW 1.03a is available since W.46 (2008). It resolved some disconnections problems with some HTC phones.
MK6100		SW : 1.03a	- SW 1.03a is available since W.49 (2008), it's resolved some disconnections problems with some HTC phones. This version is available with the PSUT

Parrot MINIKIT range

MINIKIT		SW : 1.05	- SW 1.05 is available since W24 and available on PSUT. This software resolve bugs with some Nokia phones
MINIKIT Slim Chic		SW : 1.17	- SW 1.17 is available since W.49 and now available on PSUT

MINIKIT: 1.05

The software version is now available on our website (PSUT): **1.05**

General improvements:

Fix disconnection issue with some Nokia phones.
Note: Issue still presents on Nokia 6120c, Nokia N78, Nokia 2760, and Nokia 6085

Languages available :
Language Zone: B, C, D, E, G, H
Zone F (Japanese) : soon available.

MINIKIT Slim:
The **SW1.17** is available on our website (PSUT).

TTS availability?
- British English (EN) / American English (US) / French (FR) / German (GE) / Italian (IT) / Spanish (SP) / Dutch (NL) / Mexican (ME) / Portuguese (PT)

Main improvements :
Modification list:
- No main change.

Parrot SK4000

SK4000		SW : 1.15 SW : 1.15a	The SW 1.15 is available since W14. This version is available on PSUT since end of W16
--------	--	-------------------------	---

SK4000: 1.15
This version **1.15** is available on PSUT.

Release note:
- Add audio feedback for buttons push
- Fix RF controller initialization issue

TTS availability
- British English (EN) / American English (US) / French (FR) / Spain (SP) / German (GE) / Italian (IT) / Dutch (NL) / Mexican (ME) / Portuguese (PT)

SK4000: 1.15a
This version is available on PSUT.
There is a specific software version for Spain: 1.15a with mono mode.

Release note:
- Mono mode (right speaker) is activated by default instead of stereo mode.

TTS availability
- Spanish (SP)